



Energy Storage Fuses

Product Overview

 SIBA Energy Storage (ES) Fuse Offering			
Article Number	Description	Image	
240 V_{DC} Breaking capacity 100kA			
2028204	NH000-NH00	6A-16A	
450V_{DC} Breaking capacity 30kA			
5012434	14mmx51mm	6A-40A	
5014034	22mmx58mm	6A-100A	
500V_{DC} Breaking capacity 32kA			
2021x34	NH1-NH3	40A-630A	
800V_{DC} Breaking capacity 30kA			
2055634	NH1	100A	
Contact Siba	NH1-NH3	40A-630A	
900V_{DC} Breaking capacity 226kA (L/R=2.7ms)			
2054534	SQB1-DC-082	63A - 350A	
207xx 32	SQB1-3	50A - 800A	
1000V_{DC} Breaking capacity 200kA			
5020406	14mmx51mm	20A - 25A	
5019610	27mmx60mm	20A-170A	
9008010	20mmx127mm	1-63A	
2055629	NH1	50A-200A	
2055729	NH2	200A-250A	
2056829	NH3	315A-400A	
2057529	SQB3- M12	315A-400A	
9028026	SQB3-70 With center indicator M12	400A - 900A	
9028125	SQB3-70 Without indicator US Balde		
9028126	SQB3-70 With center inidcator US blade		
9029025	SQB4 2x M12 without indicator	1000A - 2000A	
9029026	SQB4 2x M12 with center indicator		
9029125	SQB4 4x M10 without indicator		
9029126	SQB4 4x M10 with center indicator		
1100V_{DC} Breaking capacity 200kA			
2003134	NH1XL-NH3L	(40A-400A) 30kA@1000V (L/R = 10ms)	
2003134	NH1XL-NH3L	(40A-400A) 30kA@1100V (L/R = 1-3ms)	
1200V_{DC} Breaking capacity 200kA			
2002820	NH1XL with Flap Indicator	50A - 200A 1200VDC (L/R = 1ms)	
2002821	NH1XL without Indicator		
9038025	SQB3	1000A-2000A	
9039025	SQB4 2x M12 without indicator	1000A - 2000A	
9039026	SQB4 2x M12 with center indicator		
1500V_{DC}			
Contact Siba	10/14x84mm	10A-30A	
Contact Siba	NH1XL-NH3L	100A-400A	

Higher voltages and currents are available, consult with SIBA for more information.